



Customer and Market Operations
006/03.07.09
EMEA Customer Care

Service Bulletin No. SB-

RH-18

SPARE PARTS LIST AND SWAP PACKAGES (LEVEL 2)

Version history:		
Version 15	03.07.09	Code for Russia (0050394) and Ukraine (0050395) SWAP package removed
Version 14	15.04.09	Code for repair D-cover assy (9491905) removed
Version 13	05.08.08	Code for system connector (5460111) removed
Version 12	12.04.07	Code for Vibra motor changed (6800053 -> 6800049)
Version 11	11.04.07	Code for France SWAP package (0050391) removed
Version 10	22.02.07	Code for Turkey SWAP package (0050390) removed
Version 9	16.01.07	Code for Poland SWAP package (0050389) removed
Version 8	13.12.06	Code for S-Africa SWAP package (0050393) removed
Version 7	27.04.05	Code for Czech SWAP unit (0050392) removed.
Version 6	11.04.05	Code for screw changed (6290083 -> 6380231)
Version 5	06.04.04	Description for code 9491757 corrected
Version 4	05.04.04	Code for terra A-cover assy and battery cover assy added
Version 3	10.12.03	Code for LED (V321) added, code for blue A-cover assy and battery cover assy added
Version 2	22.10.03	Code for repair D-cover assy added
Version 1	15.10.03	Initial version

Note: Components in following list marked with **bold text** are new components, which have not been used in other older phone models.

		CMO / EMEA CUSTOMER CARE SALO		
		(LEVEL 2) SPARE PARTS LIST FOR		
		TRANSCEIVER RH-18 NOKIA 1100		
ITEM	CODE	DESCRIPTION	UNIT	NOTE
-	4850341	LCD ASSY 96X65 BW DMC06314 HDA11	PC	
V321	4860701	LED CL630S-WE-X 1900MCD @20MA SMD3	PC	
F100	5119019	SM FUSE F 1.5A 32V 0603	PC	
I010	514020	MIC+BOOT ASSY -42+-3DB HDA12	PC	

☐ Level 1 ☒ Level 2 ☐ Level 3 ☐ Level 4

Version 14



	1			
I005	514023 3	SPEAKER+SPRING 26+-3DB 32R D13	PC	
I013	514028 7	BUZZER ASSY DNS07652	PC	
I003	638023 1	SCREW M1.8X5.3 ISO898-1 REMFORM T6 BLACK	PC	
I012	680004 9	VIB MOT ASSY 1.3V 115MA 9500RPM	PC	
I002	949142 1	KEYMAT DMC06469 HEBREW HDA11	PC	
I002	949142 2	KEYMAT DMC06477 LATIN HDA11	PC	
I002	949142 7	KEYMAT DMC06478 CYRILLIC HDA11	PC	
I002	949142 8	KEYMAT DMC06479 GREEK HDA11	PC	
I002	949142 9	KEYMAT DMC06470 ARABIC HDA11	PC	
I019	949175 7	BATTERY COVER ASSY DMC06313 TERRA	PC	
I019	949175 8	BATTERY COVER ASSY DMC06313 BLUE	PC	
I001	949176 5	A-COVER ASSY DMC06310 BLUE HDA11	PC	
I001	949176 6	A-COVER ASSY DMC06310 TERRA HDA11	PC	
I001	949179 1	A-COVER ASSY DMC06310 JET BLACK	PC	
I019	949179 3	BATTERY COVER ASSY JET BLACK	PC	
I007	979520 0	DOMESHEET ASSY DMC06317 HDA11	PC	

Note: More detailed information e.g. about disassembly and troubleshooting can be found from Level 1 & 2 Service Manual on NOL.

Note: When repairing RH-18 phones lead free rework method must be used.

SWAP PACKAGES

CODE	DESCRIPTION
0050388	RH-18 1100 SWAP ENGINE EUROPE & AFRICA

All SWAP packages include SWAP engine without A-cover assy (I001), battery cover assy (I019) and keymat (I002).